DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Siegenthaler, Peter **Report No:** WIR-019729 Address: 333 Burma Road **Date Inspected:** 09-Jan-2011

City: Oakland, CA 94607

OSM Arrival Time: 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: Oiu Wen. **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:**

34-0006 **Bridge No: Component:** OBG components.

Summary of Items Observed:

On this day CALTRANS OSM Quality Assurance Inspector (QA) Mr. Shailesh Wadkar was present during the times noted above for observations relative to the fabrication of the Self Anchored Suspension (SAS) Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island, in Shanghai, China. QA Inspector observed and/or found the following:

Bay 14:

Notification no: 008104.

OBG Seg 13CW:

This QA inspector performed Magnetic Particle Testing (MT) of approximately 15% of an area that has been previously tested and accepted by ZPMC Quality Control (QC) personnel. This QA Inspector has generated MT report for this date. The members are identified as OBG components. The weld designations MT inspected are as follows:

- 1) FB3232-001-057, 058, 023~028.
- 2) SEG3015E-004, 059, 060, 139, 140, 142, 143.
- 3) SEG3015M-089~096.
- 4) LD3033-001-079~082, 112~115.

This QA Inspector observed the following work in progress:

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

OBG Seg 14W:

The Flux Cored Arc Welding (FCAW) process on weld joint nos: SEG3020BB-001, 028, 064 and 046 [Bottom Panel (BP) to Sub-Assembly (SA) Plate, complete joint penetration (CJP) weld]. The welders are identified as 067949, 045276, 066236 and 066695 for the respective welds and were observed welding in the 2G position. ZPMC QC was identified as Zhu Lin. The welding variables recorded by QC appeared to comply with WPS: B-T-2232-ESAB.

The FCAW process on weld joint no: SEG3020AG-008 (BP to SA Plate, CJP weld). The welders are identified as 201215 and 066734 and were observed welding in the 2G position. ZPMC QC was identified as Zhu Lin. The welding variables recorded by QC appeared to comply with WPS: B-T-2232-ESAB.

The FCAW process on weld joint no: SEG3020AG-003 [Edge Plate (EP) 3030C to Floor Beam (FB) 3329A, CJP weld, at panel point (PP) 127]. The welder is identified as 045175 and was observed welding in the 3G position. ZPMC QC was identified as Zhu Lin. The welding variables recorded by QC appeared to comply with WPS: B-T-2233-ESAB.

The Shielded Metal Arc Welding (SMAW) process on weld joint no: SEG3020G-026 (FB3334B to FB3339A, CJP weld, at PP128). The welder is identified as 047864 and was observed welding in the 1G position. ZPMC QC was identified as Zhu Lin. The welding variables recorded by QC appeared to comply with WPS: B-P-2212-B-U2-FCM.

The FCAW process on weld joint no: DP3172-001-133 [U-rib to Deck Panel (DP) diaphragm, fillet weld]. The welder is identified as 045143 and was observed welding in the 3F position. ZPMC QC was identified as Li Ping. The welding variables recorded by QC appeared to comply with WPS: B-T-2133-ESAB.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

No significant conversations were reported on this date.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang; phone: 15000422372., who represents the Office of Structural Materials for your project.

Inspected By:	Wadkar, Sailesh	Quality Assurance Inspector
Reviewed By:	Patterson, Rodney	QA Reviewer